Sanitized Copy Approved for Release 2010/03/01 : CIA-RDP80T00246A033000430001-7

PROCESSING COPY

INFORMATION REPORT INFORMATION REPORT

CENTRAL INTELLIGENCE AGENCY

Attachment No. 1 - A one-page report which describes a ferry observed south of Someri Island. Attachment No. 2 - A one-page report, with two sketches, which describes the Soviet submarine sighted at N 60-02, E 27-11, and the Soviet merchant vessel PEREKOP, undergoing repairs at Leningrad. Attachment No. 3 - A one-page report which tells of proposals to expand a quay at Leningrad to accommodate tourist liners. Attachment No. 4 three-page report, with seven sketches, which describe 8 MEN 1837 Soviet naval vessels sighted, an oil tank installation, a grain elevator, and depth soundings in Leningrad harbor. Attachment No. 5 - A one-page report containing information on naval vessels observed, including submarine and rumors of two icebreakers of 40,000 horsepower each under construction at the naval shipyard at Leningrad. Attachment No. 6 - A two-page report on naval vessel sightings, which increase and surface the port of Leningrad was busiler than it had been earlier, as demonstrated by the speed of loading. No unusual materiel or cargo was seen	-						<u>-</u> R_ጥ			25 X 1
and Fort Improvements at Leningrad and Kronshtadt NO. PAGES REFERENCES REFERENCES 25 REGUIREMENT NO. ACE & C. SOURCE EVALUATIONS ARE DEFINITIVE. APPRAISAL OF CONTENT IS TENTATIVE. Attachment No. 1 - A one-page report, with two sketches, which describes the solvent submarine sighted at N 60-02, E 27-11, and the Soviet merchant vessel PEREKOP, undergoing repairs at Leningrad to accommodate tourist liners. Attachment No. 3 - A one-page report, with seven sketches, which describes the quay at Leningrad to accommodate tourist liners. Attachment No. 4- A three-page report, with seven sketches, which describe 8 MENTEST Soviet maval vessels sighted, an oil tank installation, a grain elevator, and depth soundings in Leningrad harbor. Attachment No. 5 - A one-page report containing information on naval vessels observed, including submarine and rumors of two icebreakers of 40,000 horsepower each under construction at the naval shippard at Leningrad. Attachment No. 6 - A two-page report on naval vessel sightings, which including submarines and surface the port of Leningrad was busiler than it had been earlier, as demonstrated by the speed of lendingrad was busiler than it had been earlier, as demonstrated by the speed of lendingrad was busiler than it had been earlier, as demonstrated by the speed of lendingrad	DUNTRY	ບຣຣ	R (Lenin	grad Obl	.ast)		REPORT	<u>,</u>		
Attachment No. 2 - A one-page report which describes a ferry observed south of Someri Island. Attachment No. 2 - A one-page report, with two sketches, which describes the Soviet submarine sighted at N 60-02, E 27-11, and the Soviet merchant vessel PEREXOP, undergoing repairs at Leningrad. Attachment No. 3 - A one-page report which tells of proposals to expand a quay at Leningrad to accommodate tourist liners. Attachment No. 4r A three-page report, with seven sketches, which describe 8 Navigs7 Soviet mayal vessels sighted, an oil tank installation, a grain elevator, and depth soundings in Lentingrad harbor. Attachment No. 5 - A one-page report containing information on naval vessels observed, including submarine and rumors of two icebreakers of 40,000 horsepower each under construction at the naval shippard at Leningrad. Attachment No. 6 - A two-page report on naval vessel sightings, which includes submarines and surface the port of Leningrad was busiler than it had been earlier, as demonstrated by the speed of Leningrad was busiler than it had been earlier, as demonstrated by the speed of Leningrad	BJECT	Nav	al Sight:	ings, Po	rt Inst	tallations,	DATE DISTR.	12 Ma	rch 1957	
REFERENCES Attachment No. 1 - A one-page report which describes a ferry observed south of Someri Island. Attachment No. 2 - A one-page report, with two sketches, which describes the Soviet submarine sighted at N 60-02, E 27-11, and the Soviet merchant vessel PEREKOP, undergoing repairs at Leningrad. Attachment No. 3 - A one-page report which tells of proposals to expand a quay at Leningrad to accommodate tourist liners. Attachment No. 4- A three-page report, with seven sketches, which describe 8 MEN 1937 Soviet naval vessels sighted, an oil tank installation, a grain elevator, and depth soundings in Leningrad harbor. Attachment No. 5 - A one-page report containing information on naval vessels observed, including submarine and rumors of two icebreakers of 40,000 horsepower each under construction at the naval shipyard at Leningrad. Attachment No. 6 - A two-page report on naval vessel sightings, which increases and surface the port of Leningrad was busiler than it had been earlier, as demonstrated by the speed of loading.					.05 0.0 1	renningi au	NO. PAGES	2		
Attachment No. 2 - A one-page report which describes a ferry observed south of Someri Island. Attachment No. 2 - A one-page report, with two sketches, which describes the Soviet submarine sighted at N 60-02, E 27-11, and the Soviet merchant vessel PEREKOF, undergoing repairs at Leningrad. Attachment No. 3 - A one-page report which tells of proposals to expand a quay at Leningrad to accommodate tourist liners. Attachment No. 4x A three-page report, with seven sketches, which describe 8 MAN 1237 Soviet naval vessels sighted, an oil tank installation, a grain elevator, and depth soundings in Leningrad harbor. Attachment No. 5 - A one-page report containing information on naval vessels observed, including submarine and rumors of two icebreakers of 40,000 horsepower each under construction at the naval shippard at Leningrad. Attachment No. 6 - A two-page report on naval vessel sightings, which increase wessel the port of Leningrad and surface the port of Leningrad was busiler than it had been earlier, as demonstrated by the speed of loading.										25
Attachment No. 2 - A one-page report which describes a ferry observed south of Someri Island. Attachment No. 2 - A one-page report, with two sketches, which describes the Soviet submarine sighted at N 60-02, E 27-11, and the Soviet merchant vessel PEREKOP, undergoing repairs at Leningrad. Attachment No. 3 - A one-page report which tells of proposals to expand a quay at Leningrad to accommodate tourist liners. Attachment No. 4 three-page report, with seven sketches, which describe 8 MAIN RECO gray at Leningrad to accommodate tourist liners. Attachment No. 5 - A one-page report, with seven sketches, which describe 8 MAIN RECO gray at Leningrad harbor. Attachment No. 5 - A one-page report containing information on naval vessels observed, including submarine and rumors of two icebreakers of 40,000 horsepower each under construction at the naval shippard at Leningrad. Attachment No. 6 - A two-page report on naval vessel sightings, which increase and surface the port of Leningrad was busiler than it had been earlier, as demonstrated by the speed of loading.							REFERENCES			
Attachment No. 2 - A one-page report which describes a ferry observed south of Someri Island. Attachment No. 2 - A one-page report, with two sketches, which describes the Soviet submarine sighted at N 60-02, E 27-11, and the Soviet merchant vessel PEREKOP, undergoing repairs at Leningrad. Attachment No. 3 - A one-page report which tells of proposals to expand a quay at Leningrad to accommodate tourist liners. Attachment No. 4 three-page report, with seven sketches, which describe 8 MARIOST Soviet naval vessels sighted, an oil tank installation, a grain elevator, and depth soundings in Leningrad harbor. Attachment No. 5 - A one-page report containing information on naval vessels observed, including submarine and rumors of two icebreakers of 40,000 horsepower each under construction at the naval shippard at Leningrad. Attachment No. 6 - A two-page report on naval vessel sightings, which increase and surface vessel that it had been earlier as demonstrated by the speed of leading was busiler than it had been earlier as demonstrated by the speed of leading	CE &									25
Attachment No. 2 - A one-page report which describes a ferry observed south of Someri Island. Attachment No. 2 - A one-page report, with two sketches, which describes the soviet submarine sighted at N 60-02, E 27-11, and the Soviet merchant vessel PEREKOP, undergoing repairs at Leningrad. Attachment No. 3 - A one-page report which tells of proposals to expand a quay at Leningrad to accommodate tourist liners. Attachment No. 4 three-page report, with seven sketches, which describe 8 NATION Soviet naval vessels sighted, an oil tank installation, a grain elevator, and depth soundings in Lentingrad harbor. Attachment No. 5 - A one-page report containing information on naval vessels observed, including submarine and rumors of two icebreakers of 40,000 horsepower each under construction at the naval shippard at Leningrad. Attachment No. 6 - A two-page report on naval vessel sightings, which includes submarines and surface vessel the port of Leningrad was busiler than it had been earlier as demonstrated by the speed of leading.	E ACQ.		SOURCE EV	ALUATION	IS ARE D	EFINITIVE. API	PRAISAL OF CONTE	NT IS TENTATI	VE.	
Attachment No. 5 - A one-page report containing information on naval vessels observed, including submarine and rumors of two icebreakers of 40,000 horsepower each under construction at the naval shippard at Leningrad. Attachment No. 6 - A two-page report on naval vessel sightings, which include submarines and surface vessel the port of Leningrad was busiler than it had been earlier as demonstrated by the speed of loading.		20114								~ * ~
Attachment No. 6 - A two-page report on naval vessel sightings, which include submarines and surface vessel the port of Leningrad was buster than it had been earlier as demonstrated by the speed of loading.	Att Sov mer Att qua Att	tachme	ent No. 2 submarine vessel ent No. 3 Leningra ent No. 4 vessel ent No. 4 vessel ent No. 4 vessel ves	PEREKOP - A one d to acc A three	e-page commoda	report whice tourist	h tells of proliners. h seven sketch	E 27-11, and ad.	expand a (et 2 NIAY RECD
Attachment No. 6 - A two-page report on naval vessel sightings, which include submarines and surface vessel the port of Leningrad was buster than it had been earlier as demonstrated by the speed of loading.	Att Sov mer Att qua Att Sov dep	tachmerviet stachmerviet roth sc	ent No. 2 submarine vessel ent No. 3 Leningra ent No. 4 vessundings	- A one d to acc A three sels sti in Lentr	-page : -page : -page : -page : -page h	report which te tourist an oil tararbor.	h tells of proliners. h seven sketch k installation	E 27-11, and ad.	expand a (et 2 WAY RECD MAY RECD and H
submarines vessel and surface the port of Leningrad was buster than it had been earlier as demonstrated by the speed of leading	Att qua Att Sov dep Att obs	tachmer viet s rchant tachmer ay at tachmer viet r oth so	ent No. 2 submarine vessel ent No. 3 Leningra ent No. 4 eaval ves sundings ent No. 5 , includ orsepowe	A three sels stin Lentr	-page: -page: -page: -page: -page:	report which the tourist an oil tar arbor.	h tells of proliners. h seven sketch k installation	E 27-11, and ad.	expand a (et 2 WAY RECD MAY 1957 and 4 2
was busier than it had been earlier as demonstrated by the speed of loading.	Att Sov mer Att qua Att Sov dep Att obs 40, Len	tachmet archant tachmet archant tachmet archant roth so	ent No. 2 submarine s vessel ent No. 3 Leningra ent No. 4 saval ves sundings ent No. 5 , includ orsepowe d.	A three sels sin Lenin	e-page : commoda e-page : lghted, ngrad h	report whice tourist an oil tar arbor.	h tells of proliners. h seven sketch k installation aining informs rumors of two n at the naval	es, which can be a grain of the strong on navoration on navoration is shipyard a	expand a 3 Nexpand a 4 Nexpand a 4 Nexpand a 5 Nexpand	et 2 WAY RECD MAY RECD and H
S-E-C-R-E-T S-E-C-R-E-T AIR X MANY X MANY	Att Sov mer Att qua Att Sov dep Att obs 40, Len Att sub	tachmeter tachmeter tachmeter to the science of the	ent No. 2 submarine vessel ent No. 3 Leningra ent No. 4 eaval ves aundings ent No. 5 , includ orsepowe d. ent No. 6 es	A three sels sin Lentral A two	-page:	report whice to tourist an oil tar arbor.	at N 60-02, lars at Leningre h tells of pro- liners. h seven sketch k installation aining informs rumors of two n at the naval aval vessel si	es, which of a grain es a ghtings, when and the port of	expand a sexpand	et 2 NIAY RECD MAY 1957 and H 2
S-E-C-R-E-T E X ARMY X MAVY XAIR X FBI AEC	Att Sov mer Att qua Att Sov dep Att obs 40, Len Att. sub	tachmeter tachmeter tachmeter to the science of the	ent No. 2 submarine vessel ent No. 3 Leningra ent No. 4 aval ves sundings ent No. 5 , includ orsepowe d. ent No. 6 es er than	A three sels sin Lentral A two	e-page :	report whice te tourist an oil tar arbor.	at N 60-02, lars at Leningre h tells of pro- liners. h seven sketch k installation aining informs rumors of two n at the naval aval vessel si	es, which of the speed of the s	expand a sexpand	et 2 WAY RECU MAY RECU MAY 1937 and 4 2
E X ARMY X MAVY MAIR X FBI AEC	Att Sov mer Att qua Att Sov dep Att obs 40, Len Att. sub	tachmeter tachmeter tachmeter to the science of the	ent No. 2 submarine vessel ent No. 3 Leningra ent No. 4 aval ves sundings ent No. 5 , includ orsepowe d. ent No. 6 es er than	A three sels sin Lentral A two	e-page :	report whice te tourist an oil tar arbor.	at N 60-02, lars at Leningre h tells of pro- liners. h seven sketch k installation aining informs rumors of two n at the naval aval vessel si	es, which of the speed of the s	expand a sexpand	et 2 NIAY RECD MAY 1957 and H 2
	Att Sov mer Att qua Att Sov dep Att obs 40, Len Att sub	tachmeter tachmeter tachmeter to the science of the	ent No. 2 submarine vessel ent No. 3 Leningra ent No. 4 aval ves sundings ent No. 5 , includ orsepowe d. ent No. 6 es er than	A three sels sin Lentral A two	e-page :	report whice te tourist report, with an oil tar arbor.	at N 60-02, lars at Leningre h tells of pro- liners. h seven sketch k installation aining informs rumors of two n at the naval aval vessel si	es, which of the speed of the s	expand a sexpand	et 2 WAY RECU MAY RECU MAY 1937 and 4 2


	S-E-C-R-E-T		
	.=2=		0.5
Attachment No. 7 - A one-page r	report, with a sk	etch, which describes	25)
Soviet vessels			252
Attachment No. 8 - A two-page r describes Soviet naval vessels and harbor dredging near the Ba to form a basin for use of larg	observed in Leni altic Shipyard. se vessels to tur	ngrad and Kronshtadt, The dredging was n around in. Vessels	
observed include submarine	and surface v	essels	25X

S-E-C-R-E-T

Sanitized Copy Approved for Release 2010/03/01: CIA-RDP80T00246A033000430001-7 Attachment # 1 SECTION 25X1 Information From the USSR. LENINGRAD. Area: Time: 25X1 CAR AND PASSENGER FERRY: an inbound tugboat towing a white-painted ferry, in a position south of SOMMARS. Description of the ferry: Tonnage about 700 - 800; very high, with a painted white with a red band. The ferry is believed to be a combination car and passenger ferry; it appeared to be quite modern. 25X1 25X1







ALUME)

<u> 1</u>	nformation From the Soviet Union.	25 X 1
Area:	LENINGRAD. SECRET	
Time:		25X1
12 submands The submands point almost a detailed and other	the outer basin (COMMERCIAL HARBOUR) at KRONSTADT, 10 - rines of various sizes were seen lying at small arines were observed for only a brief period and from a most directly astern; it is therefore impossible to give add description. Aside from these, the "OOTOBER REVOLUTION", or old vessels, no other naval vessels were seen at KRONSTADT. at	
	HARPOR: the harbor at LENINGRAD was to be ex-	25X1
panded b	y a quay to accommodate large "tourist liners". The quay	
	e extended west of the PALTIC shipyard, presumably opposite	
		25 X 1



Attachment # 4


Information From the Soviet Union.	
Area: LENINGRAD.	
Time:	
3 NATE.	25X1
from a position 59 degrees,	25X1
28 minutes North by 23 degrees East, saw 10 naval vessels about	
4 neutical miles to the north. The vessels were steering a course	
of 250 degrees, true bearing.	
Description: Sketch No 1, nationality unknown, no further	
details.	
in a position 59 degrees,	25 X 1
41 minutes North by 24 degrees, 07 minutes East, a	25 X 1
naval vessel which was proceeding on various courses at various	
speeds.	
Description: Skytch No 2	25 X 1
in a position 59 degrees,	
44 minutes North by 24 degrees, 24 minutes East, 13 "torpedo boats	
end minelayers" were seen.	
Description: The nearest ones had	25X1
old type, 1 funnel, apparently armed with 3 guns, no further details.	25 X 1
off KRONSTADT passed 2 submarines.	25 X 1
Description: Sketch No 3	
A "minelayer" was seen in the same place on the same day.	
Description: 2 funnels.	25 X 1
While passing KRONSTADT the following vessels	
were seen:	
a. Some "torpedo boats"	25 X 1
10 mm	


Sanitiz	ed Copy Approved for Rele	ease 2010/03/01 : CIA-RDF	P80T00246A033000430001-7	
•				05)//
•	,			25X1
	b. A medium-siz	ed cruiser,	2 funnels.	
	c. In the roads	outside, a small "tor	pėdo boat" moored to	25 X 1
	a buoy.	one funnel.		
	d. A submarine	in the roadstead. Des	cription: Sketch No 4.	
				OEV4
	e. A small "tor	pedo boat"	one funnel.	25 X 1
	4	or 5 submarines were	seen between NARVI and	
	HOGLAND. The submari	nes were sighted at a	great distance; they	
	were sailing at great	speed in swrface posi	tion.	
	2. OIL TANKERS.			
	Farthest in at t	he southern mole in LE	NINGRAD, there is a	
	small tank installati	on; sketch No 5 shows	the location of the tanks.	
	There are 2 smal	1 wooden piers, in poo	or condition, close	to
	the 3 tanks at the le	oft the sketch. Each	ch pier is equipped with	
	a hose about	6 inches in diameter.	only the	25 X 1
	first one was in use.	The distance between	and including the two	
	piers was about 60 fe	eet.		
	3. The Grain		ay through the MORCKOY CANAL):	
	The quay is prol	oably about 1,000 feet	long, a wooden quay in	
	very poor condition,	repaired a little here	e and there. There are	
	11 loading chutes for	grain, of which the f	first 3 and the last 3	
	were not being used (possibly out of order	?)	
	4. THE KANONERSKI SI	HIPYARD:		
	4 la	rge Soviet merchant ves	ssels undergoing repairs.	25X1
	mile HADI OF			
	5. THE HARBOR:	otan of O cohomomo vid	th designation of come	
		pies of 2 echograms with		
	Landmarks. Sounding		Hughes sonic depth finder,	25X1
		rimes are given. Di	redging work was going	∠3 ∧ I


Sanitized Copy Approved for Release 2010/03/01 : CIA-RDP80T00246A033000430001-7

		J. 1. 1	
on where the quay for tourist			25)
of the BALTIC Shipyard.)	Att		
			25 X 1
			25X

- 3 **-**







Alttachment # 5	SECRA I	
e de la companya del companya de la companya de la companya del companya de la co		
Information From the Sovi	et Union.	25X1
Area: LENINGRAD.		
Time:		
1, NAVY.		
	a submarine passed in a	25 X 1
position 60 degrees, 05 minutes N	orth by 37 degrees, 13 minutes	
East. The submarine folloged a 28	O-degree course, which shortly	
thereafter was changed to 85 degr		
knots.		25 X 1
	a naval vessel was observed	
in a position 60 degrees, 11 minu	tes North, by 27 degrees, 55 minutes	
East. The vessel was steering a	course of 100 degrees. The distance	
to the vessel was very great, and	no details other than 2 masts	
and 2 funnels could be seen.		
a nav	al vessel was passed in a posi-	25 X 1
tion 59 degrees, 27 minutes, 30 s		
minutes, 50 East. The ve	ssel, which carried the lights of	
a merchant vessel, steered a cour	se of 071 degrees a speed	
of 18 knots.		
Description:		
Length about 60 feet, 2	funnels and 2 masts. About $1\frac{1}{2}$	
miles behind came a vessel of appro	owimately the same length, 2 fun-	
nels, and one mast. This vessel	carried white with a red	
one placed directly above.		
	a naval vessel was seen in	25 X 1
a position 59 degrees, 21 minutes,	40 seconds North by 23 degrees,	
05 minutes, 10 seconds East. The	vessel was steering a course of	
078 degrees, true bearing, and had	d a speed of 26 knots.	
	SEGRE (
		25X1

1 -


		521821	
	S. C. C.		25X1
Description:			
Length about 530	feet, 2 funnels	and 2 masts, 2 radar	
antennae in the foremast a	and one in the af	ter mast.	
Three miles aft of th	nis ship another	naval vessel was seen,	
which maintained the same	course and speed	1. There were 3 radar	
direction finders in the	nast.		
2. ICEBREAKERS:			
		2	
icebreakers are under con	struction in the	naval shipyard in LENIN-	25 X 1



Attachment # 6


	Information From	n the Soviet Un	nion.				
Area:	LENINGRAD.		950	B : L			25X1
1 time:							
							25X1
1. NAV	<u>4</u>	5 submarines					
	passed upbo	und on the MOVS	SK ÒT Cana	1.			
For	ur of the submar	ines seemed to	be alike	•			
De	scription:						
	On the forwar	d side of the	conning t	ower, there	was a		
step ab	out half way up	the tower. Fr	om this s	tep, one or,	, possibly,		
2 gunba	rrels protruded.	There was an	object o	n the top of	the tower.		
The	was raked	ard the after	deck.				
Th	e 5th submarine	was smaller.					051/4
							25X1
		submarines		passed out	of the		
Canal.							
				lamma marra	larecael		
	e e e e e e e e e e e e e e e e e e e	d_		large naval	r vesser		
	and anchor/ scription:	West of Knowsi	m,•				
<u>De</u>	BEI I DULIOII.	about 12,000	tons. 10	ong forward	deck with		25X1
" severa	l guns". Direct	at		superstruct			
	ise in the deckl		aft, then	re was a brea	ak to a		
	fterdeck. The					05.74	
rectly	forward of the	funnels. Q n th	ne after m	mast, there	was a lot	25X1	
of rada	r equipment and	antennae.					

to the Wa	25>
when ship was in the approximate position: 60 degrees, minutes North, by 28 degrees, 58 minutes East, No. 20	25)
it, proceeding on a westerly course at an estimated speed of	
20 knots. The vessel was escorted by 3 MTBs, one on each side and one abaft. The force disappeared in a westerly direction.	
there is greater traffic of	25)
naval vessels in the harbor than reported.	
. 4	
vessels proceeded up the Canal. Three of these vessels were alike,	
With practicelly the same	25)
	207
somewhat longer, with the same main characteristics.	
	25



Attachment # 7


	Information From the Soviet Union.	
	SECRET	25X1
Area:	LENINGRAD.	
Time:		
1. NAV	Y:	
	a naval vessel was observed	25 X 1
in a po	sition about 2 nautical miles south of LENINGRAD LIGHTSHIP.	
	7: 090 degrees; speed: 16 kmots.	
	length about 600 feet; 2 funnels;	25 X 1
and 2		
anu z	ive MT8's followed in the wake of this vessel. All these	
		25 X 1
vessel	were equipped with radar Simultaneously, 2 other vessels were sailing on a westerly	
	Simultaneously, 2 other vessels work about 220 feet in length.	
course	e farther south. The vessels were about 220 feet in length. the following vessels were	25 X 1
	the luliowing versus	23/1
seen	at KRONSTAD:	
	Old; about 3,000 tons deadweight; stern loader;	25X1
presu	mably a supply ship; painted black; portholes on three different	
	s on the side of the vessel.	
. - ·	A supply ship of about 800 tons dead weight.	25X1
	A converted cargo ship, about 1,600 tons dead weight;	
	rstructure amidships; painted gray, enqine > > 1.	
supe	Naval vessel, moored alongside another vessel of	25X1
		20,11
the	same type.	
	One large and somewhat smaller naval vessel were lying	
moo	red side by side in the big floating dock.	25X1
	۶۰ ـ غي. مينه ۱	
		_




- Attachment # 8


Information From the Soviet Union.	
	25X1
Area: LENINGRAD. SECRE	
Time:	
	25 X 1
1. NAVY.	
a submarine passed Leningrad	25 X 1
Lightship, outbound.	
Description: The coming tower had a step	25 X 1
	20/(1
in the forward side, and 2 or perhaps 3 steps in the	05)//
after side. At the	25 X 1
after edge of the tower, stood a tube with a sizable enlargement	
at the top. See sketch No 1	25X1
a naval vessel was lying at MATI SHIPYARD.	
Description: 2 gunmounts on the forecastle,	
the number of barrels could not be seen; bridge; tower with a short	
mast with radar; break from the forecastle to the main deck; fun-	
nel; boat on the deck; funnel; 2 gunmounts; transom stern with	
anchor at the hawse hole. See sketch No 2.	
a large hull was lying alongside the	25 X 1
quay at the BALTIC SHIPYARD. See sketch No 3.	
sheer toward the bow. Forward of amidships stood a cylindrical	
tower with long, oval openings at 3 different heights. On the fore-	
castle and on the afterdeck, some deckhouses had been built. At	
the after edge of the foredastle, there lay 2 cylinders which	
Source took for oil tanks of 10,000 - 15,000-liter capacity. A	
ferry or a repair ship was lying alongside the hull. No activity	25 X 1
was to be seen on board; it looked quite "dead". A sketch of the	
hull and details is shown on sketch No 4 and 5;	25X1
SECRET	


		Singli	
		a tugboat was seen	
towing 4 naval	vessels past the Custom	s Quay, out of MORSKOY CANAL.	
Descriptio	n: The vessels were al	ike. Low bridge superstruc-	
ture on the for	edeck, break from the f	orecastle to the deck approx-	
		r turrets on the afterdeck.	
-		cause of darkness. Sketch	
	No 5] shows the ster		
		an "auxiliary vessel"	
was lying at KF	RONSTAD.	See sketch	
• •	agside of this vessel la		
10 0]. 1201		scerned. On the same occasion,	
		than the rest, were seen	
		onar one rest, were been	
at KRONSTAD. N	No description.		
A large na	aval vessel was lying in	n the big floating dock at	
KRONSTAD. The	vessel was partially co	oncealed by the dock. Those	
details which	could be seen are shown	in sketch No 7].	
At about (0945 hours GMT on 17 Nov	vember, a naval vessel put	
out from KRONS	MAD on a westerly course	e toward Leningrad Lightship.	
Description	on:	Flush decks; 2 guns	
on the forward	deck; bridge superstruc	cture; mast; raked funnel;	
on the forward long afterdeck		cture; mast; raked funnel;	
long afterdeck 2. THE HARBOR	. See sketch	No 8].	
long afterdeck 2. THE HARBOR	. See sketch		
long afterdeck 2. THE HARBOR	See sketch	No 8].	
long afterdeck 2. THE HARBOR Some dred BALTIC SHIPYAR	See sketch iging work was going on 1 D.	No 8].	
long afterdeck 2. THE HARBOR Some dred BALTIC SHIPYAR formed, which	See sketch iging work was going on 1 D. would be about 100 meter	No 8]. between GREBNOY and the a basin was to be	
long afterdeck 2. THE HARBOR Some dred BALTIC SHIPYAR formed, which allow the larg	See sketch iging work was going on to the sketch of the s	No 8]. between GREBNOY and the a basin was to be rs wide and deep enough to ted the harbor to turn around a re te projected dredging shown	
long afterdeck 2. THE HARBOR Some dred BALTIC SHIPYAR formed, which allow the larg	See sketch iging work was going on to the sketch of the s	No 8]. between GREBNOY and the a basin was to be rs wide and deep enough to ted the harbor to turn around	






Sanitized Copy Approved for Release 2010/03/01 : CIA-RDP80T00246A033000430001-7 .25X1 25X1 nr. 2 25X1 **SFCRFT**







Sanitized Copy Approved for Release 2010/03/01 : CIA-RDP80T00246A033000430001-7

Sanitized Copy Approved for Release 2010/03/01 : CIA-RDP80T00246A033000430001-7

25X1

Sanitized Copy Approved for Release 2010/03/01 : CIA-RDP80T00246A033000430001-7